



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 17 April 2025

Subject: Bucharest, Romania
Henri Coanda (LROP)
Cycle 2504

***Parking Stands 402R, 403, 403R, 404L, 404, 404R, 405, 405R, 406-414 are missing.
TWY C status is incorrect.***

Jeppesen Airport Moving Map and A816 formatted data for cycle 2504, effective 17 April 2025, contain incorrect data for Henri Coanda; Bucharest, Romania (LROP). Romania AIRAC AIP SUP 04/25, published 06 March 2025, effective 17 April 2025, introducing “Temporary change of movement surface configuration at Bucuresti/ Henri Coanda Airport (LROP) due to development works” has been postponed per NOTAM A1761/25.

As a result, the following changes are valid from 16:50 [UTC] on 16 April 2025 until 23:59 [UTC] 29 April 2025:

- Parking Stands 402R, 403, 403R, 404L, 404, 404R, 405, 405R, 406- 414 are added
- Parking Stands 206R, 207L, 207-211 are removed
- Construction Area (on Apron 2 and TWY C) is removed
- TWY C (east of Stand 415) is open

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Jeppesen Airport Moving Map and A816 formatted data for cycle 2504, effective 17 April 2025, will become valid on 30 April 2025. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.