



**JEPPESEN<sup>®</sup>**  
**NavData<sup>®</sup> Alert**

**!! URGENT !!**

**Date: 4 December 2024**

**Subject: Dimapur, India  
Dimapur (VEMR)  
ILS Rwy 12  
Cycle 2412**

***Procedure information incorrect***

Jeppesen NavData for cycle 2412, effective 28 November 2024, contains incorrect data for Dimapur; Dimapur, India (VEMR).

India AIP SUP 279/2024, effective 23 January 2025 contains a new ILS or LOC Rwy 12 procedure, replacing the ILS Rwy 12. Per permanent India NOTAM G1395/24, published 1 December 2024, the effective date of India AIP SUP 279/2024 was brought forward to 1 December 2024 therefore

**ILS Rwy 12 should not be used**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2413, effective 26 DEC 24. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

**Support Portal:** [support.jeppesen.com](https://support.jeppesen.com)

**E-mail:** [navdatasupport@boeing.com](mailto:navdatasupport@boeing.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

VEMR\_2412