



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2501-04E

Notification Published date: 04-02-2025

Product Affected: Navigation+

AIRAC Cycle: 2501

Effective Date: 23-01-2025

Region: PAC

Country: Taiwan

Subject: TAICHUNG/CINGCYUANGANG (RCMQ) & PENGHU (RCQC) - FAF not aligned with LOC bearing

Source: AIP 250123

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2501

TAICHUNG/CINGCYUANGANG (RCMQ) & PENGHU (RCQC)

CAUTION: The following approaches are coded in NAVBLUE databases with the FAF deviating laterally from the Localizer bearing:

RCQC ILS 20
RCMQ ILS 36-Z

These changes will be incorporated in NAVBLUE databases for cycle 2502