



# **JEPPESEN<sup>®</sup>**

## ***Airport Moving Map Alert***

**!! URGENT !!**

**Date:** 27 September 2024

**Subject:** Da Nang, Vietnam  
Da Nang Intl (VVDN)  
Cycle 2409 and 2410

***RWY 17R/35L, RWY 17L/35R, TWYs E2, E3, E4, G1, G6 status incorrect.***

Jeppesen Airport Moving Map and A816 formatted data for cycle 2409, effective 05 September 2024, and cycle 2410, effective 03 October 2024, contain incorrect data for Da Nang Intl; Da Nang, Vietnam (VVDN).

Vietnam AIP SUP 28/24 published 05 July 2024, effective 08 August 2024, introduced "Temporary suspension of RWY 35L/17R for Construction of Taxiways G2, G4 - Phase 2 at Da Nang International Airport (VVDN)" and has been shortened per NOTAM A2072/24.

Vietnam AIP SUP 34/24 published 17 September 2024, effective 05 October 2024, introduced "Construction of RWY 35R/17L at Da Nang International Airport (VVDN)".

As a result, following changes are not reflected in cycle 2409 and 2410 data:

*Following changes are valid from 10:00 [UTC] on 30 September 2024 until 23:59 [UTC] 02 October 2024:*

- **RWY 17R/35L is open**
- TWYs G1, G6 are open

*Following changes are valid from 00:00 [UTC] on 05 October 2024 until 10:00 [UTC] on 28 December 2024:*

- **RWY 17L/35R is closed**
- TWYs E2, E3, E4 are closed

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

**Support Portal:** [support.jeppesen.com](https://support.jeppesen.com)

**E-mail:** [gisdatasupport@boeing.com](mailto:gisdatasupport@boeing.com)

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

VVDN\_2409\_2410

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2411, effective 31 October 2024. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

**Support Portal:** [support.jeppesen.com](http://support.jeppesen.com)

**E-mail:** [gisdatasupport@boeing.com](mailto:gisdatasupport@boeing.com)

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.