



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 11 April 2025

Subject: Solenzara, France
Solenzara (LFKS)
Multiple procedures
Cycle 2504

Procedure information outdated

Jeppesen NavData for cycle 2504, effective 17 April 2025, contains incorrect data for Solenzara, France (LFKS). FRANCE MIL AMDT 005-25 (MIAC 2) (eff 17 APR 25) was received after the ICAO specified date for aeronautical information publication.

TACAN Rwy 18 procedure is completely revised, therefore should not be used.

RNP Z Rwy 18: waypoint **FS18Z** should read as **FKS18**.

RNP Y Rwy 18: waypoint **FS18Y** should read as **FKS18**.

RNP X Rwy 18: waypoint **FS18X** should read as **FKS18**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2505, effective 15 May 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

LFKS_2504