



!! URGENT !!

Date: 30 September 2024

Subject: Canada
Enroute Waypoint
Cycle 2410

Waypoint coordinates incorrect

Jeppesen NavData for cycle 2410, effective 3 October 2024, contains incorrect coordinates for the Enroute Waypoint NORUN. The correct coordinates for NORUN should be **N50 14.4 W096 18.5**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2411, effective 31 October 2024. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

NORUN Waypoint 2410