

Navigation Database Addendum

AIRAC 2413 – Issue 6

SUP SG SUP A11/C12 effective 19th December 2024

SGES Minga Guazu Guarani Intl

APCH ILS Y RWY 23

Due to late receipt of document, procedure ident is not updated.
Procedure ident should read ILS Y RWY 23.

Navdata will be updated effective AIRAC cycle 2501.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Monday, December 23, 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2412 – Issue 16

SUP SG SUP A11/C12 effective 19th December 2024

SGES Minga Guazu Guarani Intl

APCH ILS Y RWY 23

Due to late receipt of document, procedure ident is not updated.
Procedure ident should read ILS Y RWY 23.

Navdata will be updated effective AIRAC cycle 2501.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Monday, December 23, 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com