

Navigation Database Addendum

AIRAC 2503 – Issue 22 NOTAM A0083/25, A0084/25, A0085/25 effective 1st April 2025

UTDD Dushanbe

SID SOPNO 1J/1K, STAR PUGUS 1E

Due to late arrivial of NOTAM, following procedures **not updated**:

- STAR PUGUS 1E, crossing ALT at PUGUS shoud read **FL180 or above**.
- SID SOPNO 1J, crossing ALT at SOPNO shoud read at FL160.
- SID SOPNO 1K: crossing ALT at SOPNO shoud read at FL160.

Navdata will be updated effective AIRAC cycle 2505.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Wednesday, 2nd April 2025

All valid FSAs/NDAs are available on http://fms-info.lhsystems.com
For any inquiries, please contact fms.support@lhsystems.com



Navigation Database Addendum

AIRAC 2504 – Issue 2NOTAM A0083/25, A0084/25, A0085/25 effective 1st April 2025

UTDD Dushanbe

SID SOPNO 1J/1K, STAR PUGUS 1E

Due to late arrivial of NOTAM, following procedures **not updated**:

- STAR PUGUS 1E, crossing ALT at PUGUS should read FL180 or above.
- SID SOPNO 1J, crossing ALT at SOPNO shoud read at FL160.
- SID SOPNO 1K, crossing ALT at SOPNO shoud read at FL160.

Navdata will be updated effective AIRAC cycle 2505.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Wednesday, 2nd April 2025

All valid FSAs/NDAs are available on http://fms-info.lhsystems.com
For any inquiries, please contact fms.support@lhsystems.com