



AN AIRBUS COMPANY

NOTIFICATION BULLETIN

NAVBLUE Reference: 2506-05N

Notification Published date: 09-06-2025

Product Affected: Navigation+

AIRAC Cycle: 2506

Effective Date: 12-06-2025

Region: SPA

Country: Malaysia

Subject: BINTULU (WBGB) - RNP Y RWY 17 & RNP Z RWY 35 Approaches

Source: AIP Supp 31/25

BINTULU (WBGB) - RNP Y RWY 17 & RNP Z RWY 35 (AR) Updates:

BINTULU (WBGB)

Please Note: After confirmation from the state the following changes are required for the following approaches in **NAVBLUE** databases.

RNP Y RWY 17:

FAF GB503 should read GB510 (GB510 coordinates N03 13 30.58 E112 59 51.21).

Missed approach - Climb on heading 168° to 1200 ft AT or Above - DF to KASPA (altitude: MNM 5000 ft, left turn, speed: MAX 230kts) - Hold at KASPA (course 318°, duration 1-minute, Right turn, altitude: MNM 5000 ft, speed: MAX 230kts).

RNP Z RWY 35 (AR):

MAPt (RWY35) speed should be blank instead of MAX 185kts.

Holding Patterns

KASPA: Altitude reads MNM 5000ft instead of MNM 5500ft.