



AN AIRBUS COMPANY

## ERROR NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2412-13E

**Notification Published date:** 17-12-2024

**Product Affected:** Navigation+

**AIRAC Cycle:** 2412

**Effective Date:** 28-11-2024

**Region:** MES

**Country:** India

**Subject:** INDIRA GANDHI INTL (VIDP) - Misalignment of the Final Approach

**Source:** AIP 241003

**Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2412**

### INDIRA GANDHI INTL (VIDP)

**CAUTION:** The ILS RW28 approach has a misalignment between the fixes FI28 and PLM04 in NAVBLUE databases. The magnetic course from FI28 to PLM04 should be 284°.

**These changes will be incorporated in NAVBLUE databases for cycle 2413**